

# ISO 11872:2024-11 (E)

## Gas welding equipment - Decomposition blockers for high-pressure acetylene

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Design .....</b>	<b>2</b>
<b>5</b>	<b>Requirements .....</b>	<b>2</b>
<b>5.1</b>	<b>Materials .....</b>	<b>2</b>
<b>5.2</b>	<b>External gas tightness .....</b>	<b>2</b>
<b>5.3</b>	<b>Pressure resistance .....</b>	<b>2</b>
<b>5.4</b>	<b>Acetylene decomposition .....</b>	<b>2</b>
<b>6</b>	<b>Type tests .....</b>	<b>2</b>
<b>6.1</b>	<b>General .....</b>	<b>2</b>
<b>6.2</b>	<b>Reference values and accuracy of instruments .....</b>	<b>3</b>
<b>6.3</b>	<b>Test gases .....</b>	<b>3</b>
<b>6.4</b>	<b>External gas tightness .....</b>	<b>3</b>
<b>6.5</b>	<b>Acetylene decomposition test .....</b>	<b>3</b>
<b>6.5.1</b>	<b>General .....</b>	<b>3</b>
<b>6.5.2</b>	<b>Test conditions .....</b>	<b>3</b>
<b>6.5.3</b>	<b>Test procedure and test precautions .....</b>	<b>4</b>
<b>6.6</b>	<b>Pressure resistance test .....</b>	<b>5</b>
<b>7</b>	<b>Manufacturer's instructions .....</b>	<b>5</b>
<b>8</b>	<b>Marking .....</b>	<b>5</b>
<b>Bibliography .....</b>		<b>7</b>