

# ISO/TR 22824:2024-12 (E)

## Welding - Best practices for specification and measurement of ferrite in stainless steel weld metal

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Metallurgical phenomena of ferrite in stainless steel weld metal .....	2
4.1	General .....	2
4.2	Solidification mode .....	3
4.2.1	General .....	3
4.2.2	A solidification mode (austenitic) .....	3
4.2.3	AF solidification mode (primary austenite) .....	3
4.2.4	FA solidification mode (primary ferrite) .....	3
4.2.5	F solidification mode (ferritic) .....	4
4.2.6	Mixed solidification modes .....	4
4.3	Solid state phase transformation of ferrite to austenite .....	5
4.3.1	General .....	5
4.3.2	A solidification mode alloys .....	6
4.3.3	AF solidification mode alloys .....	6
4.3.4	FA solidification mode alloys .....	6
4.3.5	F solidification mode alloys .....	7
4.4	Constitution diagrams .....	7
4.5	Effects of welding conditions on ferrite .....	11
4.5.1	General .....	11
4.5.2	Welding conditions which affect chemical composition .....	12
4.5.3	Welding conditions which don't affect chemical composition .....	13
4.6	Alpha prime and intermetallic phase formation .....	13
4.7	Chromium nitrides and secondary austenite .....	14
4.8	Postweld heat treatment .....	14
5	Effects of ferrite variations on service performance of stainless steel weld metal .....	15
5.1	General .....	15
5.2	Tensile properties at ambient temperatures .....	16
5.3	Toughness .....	16
5.4	Resistance to chloride stress corrosion cracking (CSCC) .....	16
5.5	Susceptibility to corrosion in certain media .....	17
5.6	Creep resistance .....	17
6	Measurement of ferrite in stainless steel weld metal .....	18
6.1	General .....	18
6.2	Considerations in ferrite measurement .....	19
6.3	Metallographic percent ferrite by optical methods .....	19
6.4	Metallographic measurement of ferrite by EBSD .....	20
6.5	Ferrite measurement by x-ray diffraction .....	20
6.6	Ferrite measurement by electrochemical dissolution of austenite .....	20
6.7	Ferrite measurement by saturation magnetization .....	20
6.8	Ferrite measurement by magnetic attraction .....	20

6.9	Measurement by magnetic permeability (magnetic induction) .....	21
6.10	Location and volume of measurement .....	22
6.11	Measurement in the HAZ .....	23
6.12	Reproducibility of measurement .....	23
6.13	Correlations between Ferrite Number and ferrite percent .....	23
7	Specification of ferrite in stainless steel weld metal .....	24
7.1	General .....	24
7.2	Non-magnetic requirements .....	25
7.3	Service environments in which ferrite is aggressively attacked .....	25
7.4	Cryogenic applications requiring weld metal toughness .....	25
7.5	High temperature service .....	26
7.6	Dissimilar welds .....	26
7.7	Buffer layers and cladding .....	26
7.8	Duplex ferritic-austenitic welds .....	27
8	Outliers in ferrite measurement .....	27
9	Conclusions .....	28
	Bibliography .....	30