

# ISO 13919-2:2001-10 (E)

Welding\_ - Electron and laser beam welded joints; Guidance on quality levels for imperfections\_-  
Part\_2: Aluminium and its weldable alloys

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>v</b>
<b>Introduction</b> .....		<b>v</b>
<b>1 Scope</b> .....		<b>1</b>
<b>2 Normative references</b> .....		<b>1</b>
<b>3 Symbols</b> .....		<b>2</b>
<b>4 Evaluation of welds</b> .....		<b>2</b>
<b>Annex A (informative)</b> .....		<b>10</b>