

# ISO 15618-2:2001-12 (E)

## Qualification testing of welders for underwater welding\_ - Part\_2: Diver-welders and welding operators for hyperbaric dry welding

---

### Contents

	Page
<b>Foreword</b> .....	v
<b>Introduction</b> .....	1
<b>1 Scope</b> .....	1
<b>2 Normative references</b> .....	1
<b>3 Terms and definitions</b> .....	3
<b>4 Symbols and abbreviations</b> .....	3
4.1 General .....	3
4.2 Test piece .....	3
4.3 Consumable .....	3
4.4 Miscellaneous .....	3
<b>5 Essential variables for approval testing</b> .....	4
5.1 General .....	4
5.2 Welding processes .....	4
5.3 Joint types (butt and fillet welds) .....	4
5.4 Material groups .....	4
5.5 Consumables .....	4
5.6 Dimensions .....	5
5.7 Welding positions .....	5
5.8 Hyperbaric environment .....	5
<b>6 Range of approval</b> .....	5
6.1 General .....	5
6.2 Welding process .....	6
6.3 Joint types .....	6
6.4 Material groups .....	7
6.5 Consumables .....	7
6.6 Dimensions .....	7
6.7 Welding positions .....	7
6.8 Hyperbaric environment .....	8
<b>7 Examination and testing</b> .....	9
7.1 General .....	9
7.2 Supervision .....	9
7.3 Shapes and dimensions of test pieces .....	9
7.4 Welding conditions .....	11
7.5 Test methods .....	11
7.6 Test pieces and test specimens .....	12
<b>8 Acceptance requirements for test pieces</b> .....	16
<b>9 Re-tests</b> .....	16
<b>10 Period of validity</b> .....	17
10.1 Initial approval .....	17
10.2 Prolongation .....	17
<b>11 Certificate</b> .....	17
<b>12 Designation</b> .....	18
<b>Annex A</b> (informative) Diver-welder or welding operator approval test certificate for hyperbaric dry welding .....	19
<b>Annex B</b> (informative) Job knowledge .....	21