

ISO 9692-4:2003-08 (E)

Welding and allied processes - Recommendations for joint preparation - Part 4: Clad steels

Contents		Page
Foreword		v
1	Scope	1
2	Normative references	1
3	Materials	1
4	Types of joint preparation	1
Table 1 -- Joint preparation for clad steels welded from both sides		2
Table 2 -- Joint preparation for clad steels welded from both sides with cladding removal		4
Table 3 -- Joint preparation for clad steels welded from one side		6
Table 4 - Joint preparation for clad steels incorporating a backing, insert or cover strip		8
Bibliography		10