

ISO 15614-10:2005-02 (E)

Specification and qualification of welding procedures for metallic materials - Welding procedure test - Part 10: Hyperbaric dry welding

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Preliminary welding procedure specification (pWPS)	2
5	Welding procedure test	3
6	Test piece	3
6.1	General	3
6.2	Shape and dimensions of test pieces	3
6.3	Welding of test pieces	3
7	Examination and testing	4
7.1	Extent of testing	4
7.2	Location and cutting of test specimens	4
7.3	Non-destructive testing	4
7.4	Destructive tests	4
7.5	Re-testing	4
8	Range of qualification	4
8.1	General	4
8.2	Related to the manufacturer	5
8.3	Related to the parent material	5
8.4	Common to all welding procedures	5
8.5	Specific to processes	7
8.6	Specific to hyperbaric environment	7
9	Welding procedure qualification record (WPQR)	8