

ISO 17657-4:2005-09 (E)

Resistance welding - Welding current measurement for resistance welding - Part 4: Calibration system

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Construction of calibration system	2
4.1 Reference welding current measuring system	2
4.2 Test set-up	2
4.3 Basic feature for calibration of welding current measuring system	2
4.4 Basic feature for calibration of current sensor	4
4.5 Basic feature for calibration of welding current meter without sensor	5
5 Physical environment and operating conditions	6
6 Calibration requirements	6
6.1 Reference welding current measuring system	6
6.2 Reference current sensor	6
6.3 Data acquisition device	7
6.4 Test stage and power sources	7
7 Test report	7
7.1 Test report for calibration of welding current measuring systems	7
7.2 Test report for calibration of current sensors	8
7.3 Test report for calibration of welding current meters without sensors	8
8 Test procedure	9
8.1 General	9
8.2 Calibration of welding current measuring system	9
8.3 Calibration of current sensor	10
8.4 Calibration of welding current meter without sensor	10
8.5 Special calibration cases	10
Annex A (informative) Measuring set-up	12
Annex B (informative) Items to be recorded or filed as reference documentation for calibration	17