

# DIN EN 482:2012-06 (E)

## Workplace exposure - General requirements for the performance of procedures for the measurement of chemical agents

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
<b>1</b>	<b>Scope .....</b>	<b>5</b>
<b>2</b>	<b>Normative references .....</b>	<b>5</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>6</b>
<b>4</b>	<b>Classification .....</b>	<b>6</b>
4.1	General .....	6
4.2	Screening measurements of time weighted average concentration .....	6
4.3	Screening measurements of variation of concentration in time and/or space .....	6
4.4	Measurements for comparison with (occupational exposure) limit values and periodic measurements .....	6
<b>5</b>	<b>Performance requirements .....</b>	<b>6</b>
5.1	General .....	6
5.2	Screening measurements of time weighted average concentration .....	7
5.3	Screening measurements of variation of concentration in time and/or space .....	7
5.4	Measurements for comparison with limit values and periodic measurements .....	7
5.4.1	Unambiguity .....	7
5.4.2	Selectivity .....	7
5.4.3	Averaging time .....	7
5.4.4	Measuring range .....	7
5.4.5	Expanded uncertainty .....	8
5.5	Composite procedures .....	8
5.6	Transport and storage .....	8
5.7	Environmental conditions .....	8
5.8	Description of measuring procedure .....	9
5.9	Dimension of result .....	9
5.10	Additional requirements .....	9
<b>6</b>	<b>Test method .....</b>	<b>9</b>
<b>7</b>	<b>Validation report .....</b>	<b>10</b>
<b>Annex A (informative) Structure of a method description .....</b>		<b>11</b>
<b>Annex B (informative) Calculation of uncertainty of measurement .....</b>		<b>12</b>
<b>B.1</b>	<b>General .....</b>	<b>12</b>
<b>B.2</b>	<b>Uncertainty associated with sampled air volume or mass uptake .....</b>	<b>13</b>
<b>B.3</b>	<b>Uncertainty associated with sampling efficiency .....</b>	<b>15</b>
<b>B.4</b>	<b>Uncertainty associated with sample storage and transportation .....</b>	<b>17</b>
<b>B.5</b>	<b>Uncertainty associated with method recovery for gases and vapours .....</b>	<b>17</b>
<b>B.6</b>	<b>Uncertainty associated with analytical recovery for airborne particles and mixtures of airborne particles and vapour .....</b>	<b>17</b>
<b>B.7</b>	<b>Uncertainty associated with method variability for gases and vapours .....</b>	<b>18</b>

<b>B.8</b>	<b>Uncertainty associated with analytical variability for airborne particles and mixtures of airborne particles and vapour .....</b>	<b>18</b>
<b>B.9</b>	<b>General equation for combination of uncertainty components .....</b>	<b>18</b>
	<b>Bibliography .....</b>	<b>20</b>