

# ISO 15202-2:2012-02 (E)

## Workplace air - Determination of metals and metalloids in airborne particulate matter by inductively coupled plasma atomic emission spectrometry - Part 2: Sample preparation

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	2
3	Terms and definitions .....	2
4	Principle .....	4
5	Requirements .....	4
6	Reactions .....	4
7	Reagents .....	5
8	Laboratory apparatus .....	5
9	Procedure .....	6
9.1	Soluble metal and metalloid compounds .....	6
9.2	Total metals and metalloids and their compounds .....	6
9.3	Mixed exposure .....	6
10	Special cases .....	7
10.1	Action to be taken if there is doubt about the effectiveness of the selected sample dissolution method .....	7
10.2	Action to be taken when particles have become dislodged from the filter during transportation	7
10.3	Action to be taken regarding sampler wall deposits .....	7
11	Laboratory records .....	7
Annex A (informative)	Safety precautions to be observed when using hydrofluoric and perchloric acids ...	8
Annex B (normative)	Sample dissolution method for soluble metal and metalloid compounds .....	9
Annex C (normative)	Sample dissolution using nitric acid and hydrochloric acid on a hotplate .....	15
Annex D (normative)	Sample dissolution using hydrofluoric and nitric acids and ultrasonic agitation .	19
Annex E (normative)	Sample dissolution using sulfuric acid and hydrogen peroxide on a hotplate .....	22
Annex F (normative)	Sample dissolution using nitric acid and perchloric acid on a hotplate .....	26
Annex G (normative)	Sample dissolution in a closed vessel microwave dissolution system .....	30
Annex H (normative)	Sample dissolution at 95 °C using a hot block .....	35

<b>Annex I (normative) Action to be taken when there is visible, undissolved, particulate material after sample dissolution .....</b>	<b>38</b>
<b>Annex J (informative) Sampler wall deposits .....</b>	<b>43</b>
<b>Bibliography .....</b>	<b>45</b>