

# ISO 13856-2:2013-04 (E)

## Safety of machinery - Pressure-sensitive protective devices - Part 2: General principles for design and testing of pressure-sensitive edges and pressure-sensitive bars

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>4</b>	<b>Requirements for design and testing .....</b>	<b>7</b>
4.1	Effective sensing surface .....	7
4.2	Actuating force for testing .....	9
4.3	Pre-travel .....	10
4.4	Working travel .....	10
4.5	Overtravel .....	10
4.6	Force .....	10
	travel relationships .....	10
4.7	Minimum operating speed .....	12
4.8	Number of operations .....	12
4.9	Sensor output .....	13
4.10	Response of output signal switching device to actuating force .....	13
4.11	Reset function .....	13
4.12	Environmental conditions .....	14
4.13	Power supply variations .....	15
4.14	Electrical equipment .....	15
4.15	Hydraulic equipment .....	16
4.16	Pneumatic equipment .....	16
4.17	Enclosure .....	16
4.18	Additional coverings for sensors .....	17
4.19	Access .....	17
4.21	Adjustments .....	18
4.22	Sensor fixing and mechanical strength .....	18
4.23	Recovery after deformation .....	18
4.24	Connections .....	19
4.25	Sharp corners, sharp edges and rough surfaces .....	19
4.26	Mechanical features .....	19
4.27	Inhibition and blocking .....	19
<b>5</b>	<b>Marking .....</b>	<b>19</b>
<b>6</b>	<b>Information for selection and use .....</b>	<b>20</b>
6.1	General .....	20
6.2	Essential data for the selection of suitable pressure-sensitive edge or pressure-sensitive bar .....	20
6.3	Information for use .....	21
<b>7</b>	<b>Verification of requirements .....</b>	<b>23</b>

7.1	General .....	23
7.2	Test samples .....	24
7.3	Test pieces .....	24
7.4	Test No. 1 -- Safety-related data for selection, installation, commissioning, operation and maintenance of suitable pressure-sensitive edges or pressure-sensitive bars .....	25
7.5	Test No. 2 -- Mounting orientations of sensors .....	25
7.6	Test No. 3 -- Actuating force .....	26
7.7	Test No. 4 -- Force .....	
	travel relationship(s) .....	32
7.8	Test No. 5 -- Number of operations .....	32
7.9	Test No. 6 -- Output state of sensor and output signal switching device .....	33
7.10	Test No. 7 -- Response of output signal switching device to actuating force, reset and state of power supply .....	33
7.11	Test No. 8 -- Environmental conditions .....	33
7.12	Test No. 9 -- Power supply variation .....	35
7.13	Test No. 10 -- Electrical, hydraulic and pneumatic equipment .....	36
7.14	Test No. 11 -- Enclosure .....	36
7.15	Test No. 12 -- Additional coverings for sensors .....	36
7.16	Test No. 13 -- Access .....	36
7.18	Test No. 15 -- Adjustments .....	37
7.19	Test No. 16 -- Sensor fixing and mechanical strength .....	37
7.20	Test No. 17 -- Recovery after deformation .....	37
7.21	Test No. 18 -- Connections .....	37
7.22	Test No. 19 -- Sharp corners, sharp edges and rough surfaces .....	37
7.23	Test No. 20 -- Mechanical features .....	37
7.24	Test No. 21 -- Inhibition and blocking .....	38
7.25	Test No. 22 -- Marking .....	38
7.26	Test No. 23 -- Information for selection and use .....	38
	Annex A (normative) Timing diagrams for pressure-sensitive edges/bars with/without reset .....	39
	Annex B (informative) Operating speed, force and travel -- Explanatory remarks and recommendations .....	43
	Annex C (informative) Device selection guidance for machinery manufacturer/user .....	46
	Annex D (informative) Design guidance .....	48
	Annex E (informative) Application guidance .....	51
	Annex F (informative) Guidance on commissioning and testing after installation .....	52
	Bibliography .....	55