

# ISO 16258-2:2015-09 (E)

## Workplace air - Analysis of respirable crystalline silica by X-ray diffraction - Part 2: Method by indirect analysis

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>3.1</b>	<b>General definitions .....</b>	<b>1</b>
<b>3.2</b>	<b>Sampling definitions .....</b>	<b>2</b>
<b>3.3</b>	<b>Analytical definitions .....</b>	<b>3</b>
<b>3.4</b>	<b>Statistical terms .....</b>	<b>4</b>
<b>4</b>	<b>Principle .....</b>	<b>5</b>
<b>5</b>	<b>Sampling .....</b>	<b>5</b>
<b>5.1</b>	<b>Sampling equipment .....</b>	<b>5</b>
<b>5.1.1</b>	<b>Samplers .....</b>	<b>5</b>
<b>5.1.2</b>	<b>Collection substrates .....</b>	<b>6</b>
<b>5.1.3</b>	<b>Sampling pumps .....</b>	<b>7</b>
<b>5.1.4</b>	<b>Flow meters .....</b>	<b>7</b>
<b>5.1.5</b>	<b>Other equipment required .....</b>	<b>8</b>
<b>5.2</b>	<b>Sample collection .....</b>	<b>8</b>
<b>5.3</b>	<b>Transport .....</b>	<b>9</b>
<b>6</b>	<b>Analytical procedure .....</b>	<b>10</b>
<b>6.1</b>	<b>Apparatus and equipment .....</b>	<b>10</b>
<b>6.1.1</b>	<b>Instrument .....</b>	<b>10</b>
<b>6.1.2</b>	<b>Balance .....</b>	<b>10</b>
<b>6.1.3</b>	<b>Laboratory equipment .....</b>	<b>10</b>
<b>6.1.4</b>	<b>Equipment to recover dust from the air sample filter .....</b>	<b>10</b>
<b>6.1.5</b>	<b>Standard reference materials .....</b>	<b>10</b>
<b>6.1.6</b>	<b>Reagents .....</b>	<b>10</b>
<b>6.1.7</b>	<b>Drift correction sample .....</b>	<b>11</b>
<b>6.2</b>	<b>Gravimetric analysis for respirable dust .....</b>	<b>11</b>
<b>6.3</b>	<b>X-ray diffraction analysis .....</b>	<b>11</b>
<b>6.3.1</b>	<b>Instrumental parameters .....</b>	<b>11</b>
<b>6.3.2</b>	<b>Scan parameters .....</b>	<b>11</b>
<b>6.4</b>	<b>Calibration curve .....</b>	<b>11</b>
<b>6.5</b>	<b>Sample treatment of collection substrate .....</b>	<b>13</b>
<b>6.5.1</b>	<b>PVC and MCE filters .....</b>	<b>13</b>
<b>6.5.2</b>	<b>Cellulose nitrate filters .....</b>	<b>14</b>
<b>6.5.3</b>	<b>Polyurethane foams .....</b>	<b>14</b>
<b>6.6</b>	<b>Redeposition onto analysis filter .....</b>	<b>15</b>
<b>6.6.1</b>	<b>Crucibles from the furnace .....</b>	<b>15</b>
<b>6.6.2</b>	<b>Bottles or beakers from a plasma asher .....</b>	<b>15</b>
<b>6.7</b>	<b>Sample analysis .....</b>	<b>15</b>
<b>7</b>	<b>Calculation .....</b>	<b>16</b>
<b>7.1</b>	<b>Gravimetric analysis .....</b>	<b>16</b>

7.2	X-ray diffraction analysis .....	16
7.3	Concentration of RCS .....	17
8	Performance characteristics .....	17
8.1	Limit of detection .....	17
8.2	Minimum detectable value .....	18
8.3	Limits of quantification .....	18
8.4	Uncertainty .....	18
8.5	Differences between samplers .....	18
8.6	Differences between analytical approaches .....	19
9	Test report .....	19
	Annex A (normative) Sample treatment strategies .....	20
	Annex B (informative) Example instrumental conditions .....	22
	Annex C (informative) Data collection parameters .....	23
	Annex D (normative) Correction for absorption .....	24
	Annex E (informative) Range of typical detection limits .....	26
	Annex F (informative) Typical expanded uncertainty of the indirect method .....	27
	Annex G (informative) Differences between samplers .....	28
	Bibliography .....	29