

# ISO 20581:2016-11 (E)

## Workplace air - General requirements for the performance of procedures for the measurement of chemical agents

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	2
4	Classification .....	2
4.1	General .....	2
4.2	Screening measurements of time-weighted average concentration .....	2
4.3	Screening measurements of variation of concentration in time and/or space .....	2
4.4	Measurements for comparison with occupational exposure limit values .....	2
4.5	Periodic measurements .....	2
5	Performance requirements .....	3
5.1	General .....	3
5.2	Screening measurements of time-weighted average concentration .....	3
5.3	Screening measurements of variation of concentration in time and/or space .....	3
5.4	Measurements for comparison with limit values and periodic measurements .....	3
5.4.1	Unambiguity .....	3
5.4.2	Selectivity .....	3
5.4.3	Averaging time .....	4
5.4.4	Measuring range .....	4
5.4.5	Expanded uncertainty .....	4
5.4.6	Chemical agents where compliant methods are not available .....	4
5.5	Composite procedures .....	4
5.6	Transport, handling and/or storage .....	5
5.7	Environmental conditions .....	5
5.8	Description of measuring procedure .....	5
5.9	Dimension of result .....	5
5.10	Additional requirements .....	5
6	Test method .....	6
7	Validation report .....	7
Annex A (informative)	Structure of a method description .....	8
Annex B (informative)	Calculation of uncertainty of measurement .....	9
Bibliography .....		16