

ISO 15202-1:2000-02 (E)

Workplace air - Determination of metals and metalloids in airborne particulate matter by inductively coupled plasma atomic emission spectrometry - Part 1: Sampling

Contents		Page
Foreword		iv
Introduction		v
1 Scope		1
2 Normative references		1
3 Terms and definitions		2
4 Principle		5
5 Requirement		5
6 Sampling equipment		5
7 Occupational exposure assessment		7
8 Sampling method		9
9 Documentation		12
Annex A (informative) Guidance on filter selection		14
Annex B (informative) Temperature and pressure correction for the indicated volumetric flow rate .		16
Bibliography		17