

DIN EN 14031:2021-09 (E)

Workplace exposure - Quantitative measurement of airborne endotoxins

Contents		Page
European foreword		3
Introduction		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Requirements	6
4.1	Skills needed for sampling	6
4.2	Sampling	7
4.2.1	General	7
4.2.2	Equipment	7
4.2.3	Filters	7
4.3	Sample transport	7
4.4	Sample storage at the laboratory	8
4.5	Glassware	8
4.6	Extraction liquids, water and detergents	8
4.7	Test for contamination	8
4.8	Sampling documentation	8
5	Extraction	9
5.1	General	9
5.2	Equipment	9
5.3	Procedure	9
5.4	Storage conditions	10
5.5	Documentation of extraction	10
6	Analytical method	10
6.1	General	10
6.2	Equipment	11
6.3	Procedure	11
6.3.1	Measurement	11
6.3.2	Calibration	11
6.3.3	Calculation	11
6.4	Validation	12
6.5	Documentation of analysis	12
7	Expression of results	12
8	Precision	13
9	Test report	13
Annex A (informative)	Properties of endotoxins and sources of occupational exposure	14
Annex B (informative)	Principle of LAL-assays	17
Annex C (informative)	Deposition of endotoxins on inner sampler walls	19
Bibliography		20