

# DIN EN 14031:2021-09 (E)

## Workplace exposure - Quantitative measurement of airborne endotoxins

---

<b>Contents</b>		<b>Page</b>
European foreword .....		3
Introduction .....		4
1	Scope .....	5
2	Normative references .....	5
3	Terms and definitions .....	5
4	Requirements .....	6
4.1	Skills needed for sampling .....	6
4.2	Sampling .....	7
4.2.1	General .....	7
4.2.2	Equipment .....	7
4.2.3	Filters .....	7
4.3	Sample transport .....	7
4.4	Sample storage at the laboratory .....	8
4.5	Glassware .....	8
4.6	Extraction liquids, water and detergents .....	8
4.7	Test for contamination .....	8
4.8	Sampling documentation .....	8
5	Extraction .....	9
5.1	General .....	9
5.2	Equipment .....	9
5.3	Procedure .....	9
5.4	Storage conditions .....	10
5.5	Documentation of extraction .....	10
6	Analytical method .....	10
6.1	General .....	10
6.2	Equipment .....	11
6.3	Procedure .....	11
6.3.1	Measurement .....	11
6.3.2	Calibration .....	11
6.3.3	Calculation .....	11
6.4	Validation .....	12
6.5	Documentation of analysis .....	12
7	Expression of results .....	12
8	Precision .....	13
9	Test report .....	13
Annex A (informative) Properties of endotoxins and sources of occupational exposure .....		14
Annex B (informative) Principle of LAL-assays .....		17
Annex C (informative) Deposition of endotoxins on inner sampler walls .....		19
Bibliography .....		20