

ISO 9951:1993-12 (E)

Measurement of gas flow in closed conduits; turbine meters

| Contents | | Page |
|-----------------|---|-------------|
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Definitions and symbols | 1 |
| 3.1 | Definitions | 1 |
| 3.2 | Symbols and subscripts | 2 |
| 4 | Principle of the method of measurement | 3 |
| 5 | Flowrates | 3 |
| 6 | Meter construction | 3 |
| 6.1 | General | 3 |
| 6.2 | Materials | 3 |
| 6.3 | Shell | 3 |
| 6.4 | Connections and maximum flowrates | 3 |
| 6.5 | Length | 3 |
| 6.6 | Pressure tapplings | 3 |
| 6.7 | Flow direction | 4 |
| 6.8 | Meter having a removable meter mechanism | 4 |
| 6.9 | Overloading | 4 |
| 6.10 | Marking | 4 |
| 7 | Pressure testing | 4 |
| 7.1 | General | 4 |
| 7.2 | Test fluid | 4 |
| 7.3 | Strength test of the pressure-containing parts | |
| 7.4 | Meter leakage test | 5 |
| 8 | Performance characteristics | 5 |
| 8.1 | Error | 5 |
| 8.2 | Calibration | 5 |
| 8.3 | Meter position | 5 |
| 8.4 | Temperature range | 5 |
| 8.5 | Pressure loss | 5 |
| 8.6 | Installation conditions | 6 |
| 8.7 | Mechanically driven external equipment | 6 |
| 9 | Output and readout | 6 |
| 9.1 | General | 6 |
| 9.2 | Counters | 6 |
| 9.3 | Flowrate Output | 6 |
| 9.4 | Mechanical Output | 6 |
| 9.5 | Voltage-free contact | 6 |
| 9.6 | Electrical pulse output | 6 |
| 9.7 | Electrical safety | 6 |
| Annexes | | |
| A | Recommendations for use | 7 |
| B | Other meter Performance characteristics | 9 |

| | |
|--|-----------|
| C Data computation and presentation | 10 |
| D Field checks | 11 |
| E Perturbations | 12 |