

ISO 15530-3:2011-10 (E)

Geometrical product specifications (GPS) - Coordinate measuring machines (CMM): Technique for determining the uncertainty of measurement - Part 3: Use of calibrated workpieces or measurement standards

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols	2
5	Requirements	3
5.1	Operating conditions	3
5.2	Similarity conditions	3
6	Principle of the uncertainty evaluation using calibrated workpieces	4
7	Procedure	4
7.1	Measuring equipment	4
7.2	Execution	4
7.3	Calculation of the uncertainty	5
7.4	Applying the substitution method: special considerations	9
8	Reverification of the measurement uncertainty	9
9	Interim check of the measurement uncertainty	10
Annex A (informative) Examples of application		11
Annex B (informative) Relation to the GPS matrix model		16
Bibliography		18