

Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms and definitions
3.1	General terms and definitions
3.2	Classification codes for drawings and data sets (see Annex B)
4	Data set identification and control
4.1	General
4.2	Related data
4.3	Data management
5	Data set requirements
5.1	General
5.1.1	Introduction
5.1.2	Fundamental requirements
5.1.2.1	General
5.1.2.2	Common to annotated models and drawings
5.1.2.3	Applicable only to models
5.1.2.4	Applicable only to drawings accompanied by 3D models
5.1.3	Design model requirement (classification codes 3, 4 and 5)
5.2	General model requirements
5.2.1	Associativity
5.2.2	Model coordinate systems
5.2.3	Applications of supplemental geometry
5.2.4	Part features not fully modelled
5.3	General method requirements
5.3.1	Data set methods
5.3.2	Model-only method
5.3.3	Model and drawing method
5.4	Management data
5.4.1	General
5.4.2	Management data in the data set
5.4.3	Management data on a model
5.5	Protection marking
5.5.1	General
5.5.2	Location on models
5.6	Saved views on models
5.6.1	General
5.6.2	Sections
6	Design model requirements
6.1	General
6.2	Geometric scale, units and precision
6.3	Model completeness
6.4	Assembly model completeness
6.5	Part reference numbers
6.6	Identification method
6.6.1	General
6.6.2	Colour

6.6.3	Greyscale
6.6.4	Mapping
6.6.5	Transparency
6.7	Installation model completeness
7	Common requirements for product definition data
7.1	General
7.2	Common requirements
7.3	Model requirements
7.3.1	General
7.3.2	Associativity
7.3.3	Attributes
7.3.4	Annotation planes
7.3.5	Leader lines
7.3.6	Direction-dependent specifications
7.3.7	Indicating of restricted area
7.3.8	Query types
7.4	Drawing requirements
7.4.1	General
7.4.2	Orthographic views
7.4.3	Axonometric views
8	Notes and special notations
8.1	Common requirements
8.2	Model requirements
8.3	Drawing requirements
9	Model values and dimensions
9.1	General
9.2	Common requirements
9.2.1	Model value queries
9.2.2	Resolved dimensions
9.3	Model requirements
9.3.1	General
9.3.2	Theoretically exact dimensions (TEDs)
9.3.3	Size values
9.3.4	Examples of general applications
9.3.5	Chamfers
9.3.6	Depth specification
9.4	Drawing requirements for axonometric views
10	Datum applications
10.1	General
10.2	Model requirements
10.2.1	Datum systems and model coordinate systems
10.2.1.1	Introduction
10.2.1.2	Datum system and coordinate system correspondence
10.2.1.3	Display link between datum system and coordinate system
10.2.2	Identification of datums
10.2.3	Identification of restricted area application
10.2.4	Associativity of datum features and design data
10.2.5	Datum target identification and attachment
10.2.6	Multiple features establishing a datum
10.3	Drawing requirements
11	Geometric tolerances
11.1	General
11.2	Drawing requirements
11.2.1	General
12	Welds
12.1	General
12.2	Common requirements
12.2.1	Application of supplemental geometry

12.2.2	Arrow lines
12.3	Model requirements
12.3.1	Annotation plane
12.3.2	Associativity
12.3.3	Indicating extents of the weld
12.3.4	Query of weld path
12.4	Drawing requirements
13	Surface texture
13.1	General
13.2	Common requirements
13.3	Model requirements
13.3.1	Display techniques
13.3.2	Associativity
Annex A	(informative) Former practices
A.1	General
A.2	Direction-dependant tolerances
A.2.1	General
A.2.2	Represented line element
A.3	Orientation tolerances
Annex B	(informative) Classification codes for drawings and data sets
B.1	General
B.2	Application
B.3	Definitions
B.4	Classification code requirements
B.4.1	General
B.4.2	Classification code location
B.4.3	Classification code 1
B.4.4	Classification code 2
B.4.5	Classification code 3
B.4.6	Classification code 4
B.4.7	Classification code 5
Annex C	(informative) Examples
C.1	General
C.2	Examples
C.2.1	Usage of “between” symbol
C.2.2	All-around application
C.2.3	Conical surface and surface of revolution

Page count: 76