

ISO 7066-2:1988-07 (E)

Assessment of uncertainty in the calibration and use of flow measurements devices; part 2: non-linear calibration relationships

Contents		Page
0	Introduction.....	1
1	Scope and field of application	1
2	References	1
3	Definitions	1
4	Symbols and abbreviations.....	1
5	Curve fitting	2
5.1	General	2
5.2	Computational methods	3
5.3	Selecting the Optimum degree of fit.....	3
6	Uncertainty.....	4
Annexes		
A	Regression methods	5
B	Orthogonal polynomial curve fitting.....	9
C	Computer program using orthogonal polynomials.....	11
D	Examples	17
E	Finite-difference method	27