

DIN 32937:2006-07 (E)

Surveillance of measuring, testing and inspection equipment - Planning, management and use of measuring, testing and inspection equipment

Contents		Page
Foreword		3
1	Scope	3
2	Normative references	3
3	Concepts	4
4	General	4
5	Objective	5
6	Requirements	5
7	Implementation	6
7.1	Planning the inspection process for verification of product conformity	6
7.1.1	General	6
7.1.2	Inspection task	6
7.1.3	Operating conditions	6
7.1.4	Specifications	7
7.1.5	Planning the inspection process	7
7.1.6	Metrological requirements	8
7.1.7	Selection of inspection equipment	8
7.1.8	Usability of inspection equipment	9
7.1.9	Suitability of the inspection process	9
7.1.10	Allocation of inspection equipment	9
7.2	Management and documentation	10
7.2.1	General	10
7.2.2	Procedures for setting up an inspection equipment management system	10
7.2.3	Identification of inspection equipment	11
7.2.4	Equipment data	11
7.2.5	Inspection equipment management system	13
7.3	Surveillance	15
7.3.1	General	15
7.3.2	Type of surveillance (internal/external)	15
7.3.3	Verification of inspection equipment	16
7.3.4	Verification and calibration times and intervals	18
7.3.5	Marking	19
7.3.6	Maintenance and storage of inspection equipment	19
7.4	Dealing with non-conformities	19
7.5	Changing the status or scrapping of equipment	20
Annex A (informative) Criteria for evaluating testing or calibration laboratories		21
Bibliography		24