

ISO 29864:2018 (E)

Self adhesive tapes — Measurement of breaking strength and elongation at break

Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms and definitions
4	Significance and use
5	Principle
6	Apparatus
6.1	Tensile testing machine
6.2	Clamps
6.3	Cylinders
6.4	Scale
6.5	Cutting tool
7	Test sample and test pieces
8	Procedure
8.1	Testing conditions
8.2	Preparation of test pieces
8.3	Method A for non-filament tapes
8.4	Method B for filament tapes
9	Expression of results
9.1	Expression of results for non-filament tapes
9.2	Expression of results for filament tapes
10	Test report

Page count: 6