

# DIN EN 15433-6:2008-02 (E)

**Transportation loads - Measurement and evaluation of dynamic mechanical loads -  
Part 6: Automatic recording systems for measuring randomly occurring shock during  
monitoring of transports**

---

## Contents

	Page
<b>Foreword .....</b>	<b>3</b>
<b>1 Scope .....</b>	<b>5</b>
<b>2 Normative references .....</b>	<b>5</b>
<b>3 Terms and definitions .....</b>	<b>5</b>
<b>4 Requirements for automatic recording devices .....</b>	<b>7</b>
<b>4.1 Accelerometers .....</b>	<b>7</b>
<b>4.2 Signal processing .....</b>	<b>7</b>
<b>4.3 Recordings .....</b>	<b>7</b>
<b>4.3.1 Recording mode "event" .....</b>	<b>7</b>
<b>4.3.2 Recording mode "plotter" .....</b>	<b>8</b>
<b>4.4 Storage modes .....</b>	<b>9</b>
<b>4.5 Time code .....</b>	<b>9</b>
<b>4.6 Power supply .....</b>	<b>9</b>
<b>4.7 Operating and display elements .....</b>	<b>9</b>
<b>4.8 Measuring range .....</b>	<b>10</b>
<b>4.9 Error limits .....</b>	<b>10</b>
<b>4.10 Saving of data .....</b>	<b>10</b>
<b>4.11 Evidence of calibration .....</b>	<b>11</b>
<b>4.12 Environmental conditions .....</b>	<b>11</b>
<b>5 Preparation for deployment .....</b>	<b>11</b>
<b>5.1 Mounting .....</b>	<b>11</b>
<b>5.2 Setting values .....</b>	<b>11</b>
<b>6 Analysis .....</b>	<b>12</b>
<b>Annex A (informative) Example set-up of shock recording equipment .....</b>	<b>14</b>