

# ISO/TS 13530:2009-03 (E)

## Water quality - Guidance on analytical quality control for chemical and physicochemical water analysis

---

| <b>Contents</b>   |  | <b>Page</b> |
|---|--|-------------|
| Foreword .....  |  | iv          |
| <b>1</b>  | <b>Scope .....</b>   | <b>1</b>    |
| <b>2</b>  | <b>Normative references .....</b>  | <b>1</b>    |
| <b>3</b>  | <b>Terms and definitions .....</b>   | <b>2</b>    |
| <b>3.1</b>  | <b>Terms related to measurement methods .....</b>  | <b>2</b>    |
| <b>3.2</b>  | <b>Terms related to measurement results .....</b>  | <b>3</b>    |
| <b>3.3</b>  | <b>Terms related to uncertainty .....</b>  | <b>5</b>    |
| <b>4</b>  | <b>Performance characteristics of analytical systems .....</b>   | <b>5</b>    |
| <b>4.1</b>  | <b>Introduction .....</b>  | <b>5</b>    |
| <b>4.2</b>  | <b>Scope of the method .....</b>   | <b>6</b>    |
| <b>4.3</b>  | <b>Calibration .....</b>   | <b>6</b>    |
| <b>4.4</b>  | <b>Limit of detection, limit of quantification .....</b>   | <b>10</b>   |
| <b>4.5</b>  | <b>Interferences and matrix effects .....</b>  | <b>12</b>   |
| <b>4.6</b>  | <b>Accuracy (trueness and precision) and uncertainty of measurement .....</b>  | <b>14</b>   |
| <b>4.7</b>  | <b>Robustness .....</b>  | <b>14</b>   |
| <b>4.8</b>  | <b>Fitness for purpose .....</b>   | <b>15</b>   |
| <b>5</b>  | <b>Choosing analytical systems .....</b>   | <b>15</b>   |
| <b>5.1</b>  | <b>General considerations .....</b>  | <b>15</b>   |
| <b>5.2</b>  | <b>Practical considerations .....</b>  | <b>16</b>   |
| <b>6</b>  | <b>Intralaboratory quality control .....</b>   | <b>16</b>   |
| <b>6.1</b>  | <b>General .....</b>   | <b>16</b>   |
| <b>6.2</b>  | <b>Terms relating to within-laboratory quality control .....</b>   | <b>17</b>   |
| <b>6.3</b>  | <b>Control of accuracy .....</b>   | <b>17</b>   |
| <b>6.4</b>  | <b>Control of trueness .....</b>   | <b>18</b>   |
| <b>6.5</b>  | <b>Control of precision .....</b>  | <b>19</b>   |
| <b>6.6</b>  | <b>Principles of applying control charts .....</b>   | <b>21</b>   |
| <b>6.7</b>  | <b>Conclusions .....</b>   | <b>25</b>   |
| <b>6.8</b>  | <b>Control charts with fixed quality criteria (target control charts) .....</b>  | <b>27</b>   |
| <b>7</b>  | <b>Quality control in sampling .....</b>   | <b>27</b>   |
| <b>8</b>  | <b>Interlaboratory quality control .....</b>   | <b>28</b>   |
| <b>9</b>  | <b>Quality control for lengthy analytical procedures or analysis undertaken infrequently or at an ad hoc basis .....</b> | <b>28</b>   |
| <b>9.1</b>  | <b>Quality control for lengthy analytical procedures .....</b>   | <b>28</b>   |
| <b>9.2</b>  | <b>Analysis undertaken infrequently or on an ad hoc basis .....</b>  | <b>29</b>   |
| <b>Annex A (informative) Verification of the limit of detection and the limit of quantification .....</b>   |  | <b>30</b>   |
| <b>Annex B (informative) The nature and sources of analytical errors .....</b>                              |  | <b>32</b>   |
| <b>Annex C (informative) Estimating the measurement uncertainty .....</b>                                   |  | <b>35</b>   |
| <b>Annex D (informative) Example for performing quality control for lengthy analytical procedures .....</b> |  | <b>37</b>   |
| <b>Bibliography .....</b>   |  | <b>38</b>   |