

DIN EN 16123:2013-05 (E)

Characterization of waste - Guidance on selection and application of screening methods

Contents		Page
Foreword		4
1	Scope	6
2	Normative references	6
3	Terms and definitions	6
4	Principles	6
5	Typical areas for application of screening methods	7
5.1	General	7
5.2	Support of sampling/sample preparation processes	7
5.3	On-site verification	7
5.4	Monitoring of processes	7
5.5	Identification of homogeneity/heterogeneity of bulk material	7
5.6	Survey of contaminated sites (hot spot identification)	7
5.7	Identification of sources of contamination	7
5.8	Safety issue	7
6	Selecting a screening method	8
6.1	Selection criteria	8
6.1.1	Sampling/sample pretreatment/preparation	8
6.1.2	Parameter definition	8
6.1.3	Field of application	8
6.1.4	Boundary conditions	8
6.2	Fit-for-purpose test	9
6.3	Quality targets	9
7	Applicability conditions for screening methods	9
7.1	General	9
7.2	Field of application	9
7.2.1	Principle of the measurement	9
7.2.2	Instruction for method setup	10
7.2.3	Sampling and samples	10
7.2.4	Measurement steps	10
7.2.5	Statement of results	10
7.2.6	Disposal instructions	10
7.2.7	Characteristic data of the method	10
7.2.8	Literature references	11
8	Fit-for-purpose testing	11
8.1	General	11
8.2	Reproducibility testing	11
8.3	Exclusion of false negative results	11
8.4	Testing of individual comparability	12
9	Analytical acceptance criteria	12
9.1	General	12
9.2	Starting criteria	12
9.3	Continuous criteria	12

10	Quality assurance	12
11	Documentation	13
	Annex A (informative) Decision making process	14
	Annex B (informative) Example of documentation aid/check list	15
	Annex C (informative) Statistical tool for individual comparability - Equality of results from reference method and screening method: Mean value t-test for real samples	18
C.1	General	18
C.2	Test on outliers	18
C.3	Homogeneity of variances	18
C.4	Mean value t-test	19
	Bibliography	21