

DIN EN 16424:2015-03 (E)

Characterization of waste - Screening methods for the element composition by portable X-ray fluorescence instruments

Contents		Page
Foreword		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Principle	5
5	Safety remarks	6
6	Apparatus and equipment	6
6.1	X-ray fluorescence spectrometer	6
6.2	Direct measurement using a hand-held instrumentation in direct contact with the sample	7
6.3	Hand-held instrumentation mounted on a stand using sample cups filled with the sample	7
6.4	Portable bench top XRF instrument	7
6.5	Spoon, stamp and/or hammer	7
6.6	Mortar and pestle	7
6.7	Thin-film support	7
6.8	Sample cups	7
7	Calibration	7
7.1	General	7
7.2	Interferences	8
7.3	Calibration procedure	8
7.4	Validation of the calibration	9
8	Screening strategy	10
9	Sample preparation	12
9.1	General	12
9.2	Sample preparation for direct measurement	12
9.3	Sample preparation for filling cups	12
9.4	Sample preparation for heterogeneous samples	12
10	Analysis	12
10.1	General	12
10.2	Direct in situ measurement (hand-held method)	12
10.3	Measurement by using a mounted hand-held XRF instrument or a small portable closed XRF instrument	13
11	Calculation of the result	13
12	Assessment of the XRF screening measurement	13
12.1	General	13
12.2	Identification of the presence or absence of the elements under investigation	13
12.3	Indication of the concentration range of the elements under investigation	14

13	Quality control	14
13.1	Drift correction procedure	14
13.2	Blank test	14
13.3	Reference materials	14
14	Test report	15
Annex A (informative) Examples of instrumentation		16
Annex B (informative) List of analytical lines and spectral line overlaps		19
Annex C (informative) Evaluation of the acceptance criteria		20
C.1	Uncertainty	20
C.2	Test of the absence of an element	20
C.3	Test of the documented concentration of an element	20
C.4	Estimation of uncertainty	21
Annex D (informative) Validation		22
Bibliography		33