

DIN EN 16424:2015-03 (E)

Characterization of waste - Screening methods for the element composition by portable X-ray fluorescence instruments

Contents	Page
Foreword	4
1 Scope	5
2 Normative references	5
3 Terms and definitions	5
4 Principle	5
5 Safety remarks	6
6 Apparatus and equipment	6
6.1 X-ray fluorescence spectrometer	6
6.2 Direct measurement using a hand-held instrumentation in direct contact with the sample	7
6.3 Hand-held instrumentation mounted on a stand using sample cups filled with the sample	7
6.4 Portable bench top XRF instrument	7
6.5 Spoon, stamp and/or hammer	7
6.6 Mortar and pestle	7
6.7 Thin-film support	7
6.8 Sample cups	7
7 Calibration	7
7.1 General	7
7.2 Interferences	8
7.3 Calibration procedure	8
7.4 Validation of the calibration	9
8 Screening strategy	10
9 Sample preparation	12
9.1 General	12
9.2 Sample preparation for direct measurement	12
9.3 Sample preparation for filling cups	12
9.4 Sample preparation for heterogeneous samples	12
10 Analysis	12
10.1 General	12
10.2 Direct in situ measurement (hand-held method)	12
10.3 Measurement by using a mounted hand-held XRF instrument or a small portable closed XRF instrument	13
11 Calculation of the result	13
12 Assessment of the XRF screening measurement	13
12.1 General	13
12.2 Identification of the presence or absence of the elements under investigation	13
12.3 Indication of the concentration range of the elements under investigation	14

13	Quality control	14
13.1	Drift correction procedure	14
13.2	Blank test	14
13.3	Reference materials	14
14	Test report	15
	Annex A (informative) Examples of instrumentation	16
	Annex B (informative) List of analytical lines and spectral line overlaps	19
	Annex C (informative) Evaluation of the acceptance criteria	20
C.1	Uncertainty	20
C.2	Test of the absence of an element	20
C.3	Test of the documented concentration of an element	20
C.4	Estimation of uncertainty	21
	Annex D (informative) Validation	22
	Bibliography	33