

ISO 13165-3:2016-03 (E)

Water quality - Radium-226 - Part 3: Test method using coprecipitation and gamma-spectrometry

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols	2
5	Principle of the measurement	3
6	Reagents and equipment	3
6.1	Reagents	3
6.2	Equipment	4
7	Sampling	4
7.1	Sample collection	4
7.2	Sample transport and storage	4
8	Procedures	4
8.1	Blank sample preparation	4
8.2	Sample preparation	5
8.3	Counting procedure	5
9	Quality assurance and quality control programme	5
9.1	General	5
9.2	Influence quantities	6
9.3	Instrument verification	6
9.4	Method verification	6
9.5	Demonstration of analyst capability	6
10	Expression of results	6
10.1	General	6
10.2	Water-soluble ²²⁶ Ra activity concentration	7
10.3	Standard uncertainty of activity concentration	7
10.4	Decision threshold	7
10.5	Detection limit	7
10.6	Limits of the confidence interval	8
10.7	Corrections for contributions from other radionuclides and background	8
10.7.1	General	8
10.7.2	Contribution from other radionuclides	9
10.7.3	Contribution from background	10
11	Expression of results	10
Annex A (informative)	Uranium and its decay chain	12
Bibliography		14