

# DIN EN ISO 22125-2:2024-05 (E)

## Water quality - Technetium-99 - Part 2: Test method using inductively coupled plasma mass spectrometry (ICP-MS) (ISO 22125-2:2019)

---

<b>Contents</b>		<b>Page</b>
European foreword .....		3
Foreword .....		4
Introduction .....		5
<b>1</b>	<b>Scope</b> .....	<b>7</b>
<b>2</b>	<b>Normative references</b> .....	<b>7</b>
<b>3</b>	<b>Terms, definitions and symbols</b> .....	<b>8</b>
<b>4</b>	<b>Principle</b> .....	<b>10</b>
<b>5</b>	<b>Sampling, handling and storage</b> .....	<b>10</b>
<b>6</b>	<b>Procedure</b> .....	<b>10</b>
6.1	Sample preparation for measurement .....	10
6.2	Sample measurement .....	11
<b>7</b>	<b>Quality assurance and quality control program</b> .....	<b>11</b>
7.1	General .....	11
7.2	Variables that could influence the measurement .....	11
7.3	Instrument verification .....	11
7.4	Contamination .....	11
7.5	Interference control .....	12
7.6	Method verification .....	12
7.7	Demonstration of analyst capability .....	12
<b>8</b>	<b>Expression of results</b> .....	<b>12</b>
8.1	Using Re, <sup>97</sup> Tc, or <sup>98</sup> Tc as a recovery tracer .....	12
8.1.1	Calculation of mass of tracer and analyte added .....	12
8.1.2	Measurement bias .....	13
8.1.3	Sample mass concentration .....	13
8.1.4	Detection limit .....	14
8.1.5	Limit of quantification .....	14
8.2	Using <sup>95m</sup> Tc, <sup>97m</sup> Tc or <sup>99m</sup> Tc as a recovery tracer .....	14
8.2.1	Calculation of activity of tracer, mass of analyte and mass of internal standard added .....	14
8.2.2	Purification step recovery .....	15
8.2.3	Measurement bias .....	15
8.2.4	Sample mass concentration .....	15
8.2.5	Detection limit .....	15
8.2.6	Limit of quantification .....	16
8.2.7	Conversion of mass concentration to activity concentration .....	16
8.2.8	Conversion of mass concentration to volume unit .....	16
8.3	Correction for the presence of <sup>99</sup> Tc in the tracer .....	17
<b>9</b>	<b>Test report</b> .....	<b>17</b>
<b>Annex A (informative) Method 1 — TEVA resin</b> .....		<b>18</b>
<b>Annex B (informative) Method 2 — TRU resin</b> .....		<b>21</b>
<b>Annex C (informative) Method 3 — Anion exchange resin</b> .....		<b>24</b>
<b>Bibliography</b> .....		<b>27</b>