

# DIN EN ISO 13165-3:2020-12 (E)

## Water quality - Radium-226 - Part 3: Test method using coprecipitation and gamma-spectrometry (ISO 13165-3:2016)

---

<b>Contents</b>	<b>Page</b>
European foreword .....	3
Foreword .....	4
Introduction .....	5
<b>1 Scope</b> .....	<b>6</b>
<b>2 Normative references</b> .....	<b>6</b>
<b>3 Terms and definitions</b> .....	<b>6</b>
<b>4 Symbols</b> .....	<b>7</b>
<b>5 Principle of the measurement</b> .....	<b>8</b>
<b>6 Reagents and equipment</b> .....	<b>8</b>
6.1 Reagents .....	8
6.2 Equipment .....	9
<b>7 Sampling</b> .....	<b>9</b>
7.1 Sample collection .....	9
7.2 Sample transport and storage .....	9
<b>8 Procedures</b> .....	<b>9</b>
8.1 Blank sample preparation .....	9
8.2 Sample preparation .....	10
8.3 Counting procedure .....	10
<b>9 Quality assurance and quality control programme</b> .....	<b>10</b>
9.1 General .....	10
9.2 Influence quantities .....	11
9.3 Instrument verification .....	11
9.4 Method verification .....	11
9.5 Demonstration of analyst capability .....	11
<b>10 Expression of results</b> .....	<b>11</b>
10.1 General .....	11
10.2 Water-soluble <sup>226</sup> Ra activity concentration .....	12
10.3 Standard uncertainty of activity concentration .....	12
10.4 Decision threshold .....	12
10.5 Detection limit .....	13
10.6 Limits of the confidence interval .....	13
10.7 Corrections for contributions from other radionuclides and background .....	13
10.7.1 General .....	13
10.7.2 Contribution from other radionuclides .....	14
10.7.3 Contribution from background .....	15
<b>11 Expression of results</b> .....	<b>15</b>
<b>Annex A (informative) Uranium and its decay chain</b> .....	<b>17</b>
<b>Bibliography</b> .....	<b>19</b>