

# ISO 7146-2:2019 (E)

## Plain bearings — Appearance and characterization of damage to metallic hydrodynamic bearings — Part 2: Cavitation erosion and its countermeasures

---

### Contents

|       |  |
|-------|--|
|       | Foreword   |
|       | Introduction   |
| 1     | Scope  |
| 2     | Normative references   |
| 3     | Terms and definitions  |
| 4     | Cavitation erosion   |
| 4.1   | Mechanism of cavitation erosion  |
| 4.2   | Classification of cavitation erosion   |
| 4.3   | General countermeasures against cavitation erosion                             |
| 5     | Five types of cavitation erosion   |
| 5.1   | General  |
| 5.2   | Flow cavitation erosion  |
| 5.2.1 | Typical damage appearance  |
| 5.2.2 | Possible causes  |
| 5.2.3 | Possible countermeasures   |
| 5.2.4 | Typical examples (see Figures 4 to 8)  |
| 5.3   | Impact cavitation erosion  |
| 5.3.1 | Typical damage appearance  |
| 5.3.2 | Possible damage causes   |
| 5.3.3 | Possible countermeasures   |
| 5.3.4 | Typical examples (see Figures 9 to 11)   |
| 5.4   | Suction cavitation erosion   |
| 5.4.1 | Typical damage appearance  |
| 5.4.2 | Possible causes  |
| 5.4.3 | Possible countermeasures   |
| 5.4.4 | Typical examples (see Figures 12 to 14)  |
| 5.5   | Discharge cavitation erosion   |
| 5.5.1 | Typical damage appearance  |
| 5.5.2 | Possible causes  |
| 5.5.3 | Possible countermeasures   |
| 5.5.4 | Typical examples (see Figures 15 to 16)  |
| 5.6   | Miscellaneous cavitation erosion (see Figures 17 to 20)                        |
| 5.6.1 | Cavitation erosion caused by high-frequency vibration (“Vibration cavitation”) |
| 5.6.2 | Cavitation erosion by elastic bearing deformation or abnormal combustion       |
| 5.6.3 | Rippling or roughening (see Figures 19 and 20)                                 |

Page count: 18