

ISO 3547-6:2020-05 (E)

Plain bearings - Wrapped bushes - Part 6: Checking the inside diameter

Contents		Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols and units	1
5 Method of checking	2
6 Test equipment	2
6.1 Ring gauge	2
6.2 Plug gauge	3
6.3 Three-point measuring instrument	4
6.4 Requirements for measuring equipment	5
6.5 Measuring errors	5
7 Procedure	5
Bibliography	6