

ISO 3547-7:2020-05 (E)

Plain bearings - Wrapped bushes - Part 7: Measurement of wall thickness of thin-walled bushes

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and units	2
5	Purpose of checking	2
6	Checking methods	2
	6.1 Measuring principle	2
	6.2 Line measurement around the circumference	3
	6.3 Point measurement	4
7	Requirements for measuring equipment for the contact method	4
	7.1 Radius of the measuring pin on the outside surface	4
	7.2 Radius of the measuring pin on the inside surface	5
	7.3 Measuring pin load	5
8	Checking of measuring equipment	5
Bibliography		6