

ISO/IEC TR 29158:2011-10 (E)

Information technology - Automatic identification and data capture techniques - Direct Part Mark (DPM) Quality Guideline

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Abbreviated terms	2
5	Overview of methodology	3
5.1	Process differences from 15415	3
5.2	Lighting	3
6	Obtaining the image	3
6.1	Orientation of the symbol to the camera	3
6.2	Lighting	4
6.3	Image focus	4
6.4	Reflectance calibration	4
6.5	Initial image reflectance level of the symbol under test	5
7	Obtaining the test image	5
7.1	Binarize image	5
7.2	Apply Reference Decode Algorithm	5
7.3	Connect areas of the same colour	6
7.4	Final image adjustment	7
8	Determine contrast parameters	7
8.1	Calculate Cell Contrast (CC)	8
8.2	Calculate Cell Modulation (CM)	8
8.3	Calculate % Reflectance of Symbol (Rtarget)	8
9	Grading	8
9.1	Cell Contrast (CC)	8
9.2	Minimum Reflectance	8
9.3	Cell Modulation (CM)	8
9.4	Fixed pattern damage	9
9.5	Final grade	9
10	Communicating grade requirements and results	9
10.1	Communication from Application to Verifier	9
10.2	Communicating from Verifier to Application	9
10.3	Communicating Lighting	9
10.4	Communicating the use of a proprietary decode	10
Annex A (normative)	Threshold determination method	11
Annex B (informative)	Communicating the grade	15