

# DIN 66399-2:2012-10 (E)

## Office machines - Destruction of data carriers - Part 2: Requirements for equipment for destruction of data carriers

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
1	Scope .....	4
2	Normative references .....	4
3	Terms and definitions .....	4
4	Requirements .....	4
4.1	Degree of destruction .....	4
4.2	Materials referred to in security levels .....	4
4.3	Limits for particle sizes .....	4
4.4	Feed and collection apparatus .....	12
4.5	Checking that destruction is complete .....	12
5	Testing .....	12
5.1	Ambient conditions .....	12
5.2	Test material .....	12
5.3	Testing the rated throughput .....	13
5.4	Testing the degree of destruction .....	13
5.4.1	Purpose of the test .....	13
5.4.2	Feeding in the test material .....	13
5.4.3	Sample quantity .....	13
5.4.4	Sampling from destroyed test material .....	13
5.4.5	Analysis .....	13
5.4.6	Evaluation .....	14
6	Test report .....	14
7	Test certificate .....	15
Tables	Table 1 -- Information in the original size .....	6
	Table 2 -- Information in miniaturized form .....	7
	Table 3 -- Information on optical data carriers .....	8
	Table 4 -- Information on magnetic data carriers .....	9
	Table 5 -- Information on hard drives with magnetic data carriers .....	10
	Table 6 -- Information on electronic data carriers .....	11