

ISO 3353-1:2002-07 (E)

Aerospace - Lead and runout threads - Part 1: Rolled external threads

Contents		Page
Foreword		iv
1	Scope	1
2	Terms and definitions	1
3	Symbols for threads	2
4	Requirements	2
4.1	General requirements	2
4.2	Lead threads	2
4.3	Runout threads	3
5	Inspection method	7
5.1	General	7
5.2	Use of the charts	7
5.3	Procedure	8
Annex A (informative) Comments on inspection method		11