

# ISO 3353-1:2002-07 (E)

## Aerospace - Lead and runout threads - Part 1: Rolled external threads

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	Scope .....	1
2	Terms and definitions .....	1
3	Symbols for threads .....	2
4	Requirements .....	2
4.1	General requirements .....	2
4.2	Lead threads .....	2
4.3	Runout threads .....	3
5	Inspection method .....	7
5.1	General .....	7
5.2	Use of the charts .....	7
5.3	Procedure .....	8
Annex A (informative) Comments on inspection method .....		11