

ISO 21398:2007-06 (E)

Hard coal and coke - Guidance to the inspection of mechanical sampling systems

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normatives references	1
3	Terms and definitions	1
4	Safety	2
5	General considerations	2
5.1	Precision	2
5.2	Bias	2
5.3	Operation of sampling system	2
6	Establishment of inspection system	3
6.1	General	3
6.2	Audit -- External	3
6.3	Audit -- Internal	4
6.4	Operational inspections	4
7	Procedures	4
7.1	Audit -- External	4
7.2	Audit -- Internal	5
7.3	Operational inspections	6
8	Quality control	6
8.1	General	6
8.2	Sampling ratio	6
8.3	Coefficient of variation	7
8.4	Extraction ratio	7
8.5	Sampling records	7
8.6	Operators' inspection report	8
	Annex A (informative) Monitoring coal sampling ratios using control charts	11
	Annex B (informative) Examples of sampling checklists	15
	Annex C (informative) Example of sampling plant operators inspection report	18
	Annex D (informative) Example of sampling plant operations inspection summary	23
	Bibliography	25