

# ISO 5398-4:2007-08 (E)

Leather — Chemical determination of chromic oxide content —  
Part 4: Quantification by inductively coupled plasma – optical emission spectrometer (ICP-OES)

---

<b>Contents</b>		Page
<b>Foreword</b> .....		iv
<b>Introduction</b> .....		v
<b>1</b>	<b>Scope</b> .....	1
<b>2</b>	<b>Normative references</b> .....	1
<b>3</b>	<b>Terms and definitions</b> .....	1
<b>4</b>	<b>Principle</b> .....	2
<b>5</b>	<b>Sampling and sample preparation</b> .....	2
<b>6</b>	<b>Reagents</b> .....	2
<b>6.1</b>	<b>Wet oxidation method</b> .....	2
<b>6.2</b>	<b>ICP-OES</b> .....	2
<b>7</b>	<b>Apparatus</b> .....	2
<b>8</b>	<b>Methods</b> .....	3
<b>8.1</b>	<b>Preparation of analytical solution</b> .....	3
<b>8.2</b>	<b>Measurement of the aqueous solution</b> .....	3
<b>9</b>	<b>Calculation and expression of results</b> .....	4
<b>10</b>	<b>Test report</b> .....	5
<b>Annex A (informative) Determination of water and other volatile matter</b> .....		6