

# ISO 12004-1:2008-10 (E)

## Metallic materials - Sheet and strip - Determination of forming-limit curves - Part 1: Measurement and application of forming-limit diagrams in the press shop

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1 <b>Scope</b> .....		1
2 <b>Symbols and abbreviated terms</b> .....		1
3 <b>Principle</b> .....		1
4 <b>Test conditions</b> .....		2
5 <b>Procedure</b> .....		2
6 <b>Interpretation of results</b> .....		3
7 <b>Test report</b> .....		3
<b>Annex A (informative) Modification to forming-limit curves</b> .....		5
<b>Annex B (informative) Examples of grid patterns currently in use</b> .....		6
<b>Bibliography</b> .....		8