

# DIN EN ISO 14713-3:2010-05 (E)

## Zinc coatings - Guidelines and recommendations for the protection against corrosion of iron and steel in structures - Part 3: Sherardizing (ISO 14713-3:2009)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
<b>1</b>	<b>Scope .....</b>	<b>5</b>
<b>2</b>	<b>Normative references .....</b>	<b>5</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>6</b>
<b>4</b>	<b>Design for sherardizing .....</b>	<b>6</b>
4.1	General .....	6
4.2	Surface preparation .....	6
4.3	Design considerations .....	7
4.4	Clearances of threaded components .....	7
<b>5</b>	<b>Storage and transport .....</b>	<b>8</b>
5.1	General .....	8
5.2	Recommendations for storage and transport .....	8
<b>6</b>	<b>Effects of article condition on quality of sherardizing .....</b>	<b>8</b>
6.1	Composition .....	8
6.2	Surface condition .....	9
6.3	Influence of steel surface roughness on the sherardized coating thickness .....	9
6.4	Internal stresses in the base material .....	9
6.5	Large objects and thick steels .....	10
<b>7</b>	<b>Effect of sherardizing process on the article .....</b>	<b>10</b>
7.1	Processing circumstances .....	10
7.2	Coating properties influenced by the sherardizing process .....	11
<b>8</b>	<b>After-treatments .....</b>	<b>11</b>
Bibliography .....		12