

ISO 23529:2010-10 (E)

Rubber - General procedures for preparing and conditioning test pieces for physical test methods

Contents	Page
Foreword	iv
1 Scope	1
2 Identification and record keeping	1
3 Standard laboratory conditions	2
3.1 Standard laboratory temperature	2
3.2 Standard laboratory humidity	2
3.3 Other conditions	2
4 Storage of samples and test pieces	2
5 Preparation of test pieces	3
5.1 Test piece thickness	3
5.2 Thickness adjustment	3
5.3 Test piece cutters	5
5.4 Maintenance of cutters	6
5.5 Preparation of test pieces by moulding	6
6 Conditioning	7
6.1 General	7
6.2 Conditioning times for subnormal or elevated temperatures	7
7 Measurement of the dimensions of test pieces	7
7.1 Method A -- For dimensions less than 30 mm	7
7.2 Method B -- For dimensions of 30 mm and up to and including 100 mm	8
7.3 Method C -- For dimensions over 100 mm	8
7.4 Method D -- Non-contact method	8
8 Conditions of test	9
8.1 Duration of test	9
8.2 Temperature and humidity	9
9 Test chambers	10
9.1 General requirements for temperature-controlled chambers	10
9.2 Chambers operating at elevated temperatures	11
9.3 Chambers operating at subnormal temperatures	11
10 Test report	12
Annex A (normative) Conditioning times for rubber test pieces	13
Bibliography	16