

ISO 23873:2010-11 (E)

Hard coal —Method for the measurement of the swelling of hard coal using a dilatometer

Contents		Page
Foreword		iv
Introduction.....		v
1 Scope		1
2 Normative references		1
3 Terms and definitions		1
4 Principle		2
5 Materials		2
6 Apparatus		2
6.1 Mould and accessories		2
6.2 Dilatometer		3
6.3 Dilatometer furnace		3
6.4 Temperature controller		4
6.5 Temperature recorder		4
6.6 Retort and piston		4
6.7 Means of recording piston movement		4
6.8 Cleaning instruments		4
7 Procedure		5
7.1 Temperature calibration.....		5
7.2 Preparation of test sample and test pieces		5
7.3 Determination		6
8 Expression of results		7
9 Precision		8
9.1 Repeatability		8
9.2 Reproducibility		8
10 Test report.....		8