

# ISO 10810:2010-11 (E)

## Surface chemical analysis - X-ray photoelectron spectroscopy - Guidelines for analysis

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Symbols and abbreviations .....	1
5	Overview of sample analysis .....	2
6	Specimen characterization .....	4
6.1	General .....	4
6.2	Specimen forms .....	4
6.3	Material types .....	6
6.4	Handling and mounting of specimens .....	7
6.5	Specimen treatments .....	7
7	Instrument characterization[8] .....	7
7.1	General .....	7
7.2	Instrument checks .....	8
7.3	Instrument calibration .....	8
7.4	Instrument set-up .....	14
8	The wide-scan spectrum .....	15
8.1	Data acquisition .....	15
8.2	Data analysis .....	16
9	The narrow scan .....	18
9.1	General .....	18
9.2	Data acquisition .....	18
9.3	Data analysis .....	18
10	Test report .....	22
Bibliography .....		24