

# DIN EN 16016-4:2012-01 (E)

## Non destructive testing - Radiation methods - Computed tomography - Part 4: Qualification

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
1	Scope .....	5
2	Normative references .....	5
3	Terms and definitions .....	5
4	Qualification of the inspection .....	5
4.1	General .....	5
4.2	Qualification of defect testing .....	5
4.2.1	General .....	5
4.2.2	Quality feature .....	5
4.2.3	Feature detectability/test system/system parameterisation .....	6
4.2.4	Verification of suitability .....	7
4.2.5	Consistency check .....	7
4.2.6	Documentation .....	7
4.3	Qualification of dimensional testing .....	8
4.3.1	General .....	8
4.3.2	Test and measurement task .....	8
4.3.3	Dimensional testing/test system/system parameterisation .....	8
4.3.4	Degree of accuracy .....	9
4.3.5	Consistency check .....	9
4.3.6	Documentation .....	9
5	Qualification of the CT system .....	9
5.1	General .....	9
5.2	Integral overall system test .....	10
5.3	Checking the system components .....	10
5.3.1	General .....	10
5.3.2	Manipulation system .....	10
5.3.3	Image scale .....	10
5.3.4	Beam axis perpendicularity .....	10
5.3.5	Tube focal spot .....	10
5.3.6	Tube stability .....	10
5.3.7	Detector .....	11
5.3.8	Reconstruction .....	11
5.3.9	Visualisation .....	11
5.4	Documentation .....	11
6	Example of CT system resolution evaluation methods .....	11
6.1	Pre-amble .....	11
6.2	Acquisition parameters .....	12
6.3	Recommendations for creating reference objects .....	12
6.4	Density resolution measurement method .....	12
6.4.1	General .....	12
6.4.2	High energy reference object .....	13
6.4.3	Low energy reference object .....	13
6.4.4	Experimental measurements .....	13