

# DIN EN ISO 12677:2012-01 (E)

## Chemical analysis of refractory products by X-ray fluorescence (XRF) - Fused cast-bead method (ISO 12677:2011)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		4
1	Scope .....	5
2	Normative references .....	5
3	Types of material .....	5
4	Principle .....	6
5	Apparatus .....	6
6	Sample grinding .....	7
7	Loss on ignition (and/or drying) .....	8
8	Flux .....	8
8.1	Choice of flux and ratio of flux to sample .....	8
8.2	Compensations for moisture in flux .....	9
9	Fusion casting procedures .....	9
9.1	Fusion of samples and casting of beads .....	9
9.2	Automatic bead preparation .....	11
9.3	Storage .....	11
9.4	Special problems .....	12
10	Calibration .....	12
10.1	Calibration standards .....	12
10.2	Reagents and series reference materials (SeRMs) .....	12
10.3	Calibration using reagents .....	14
10.4	Calibration using SeRMs .....	19
11	Corrections .....	21
11.1	Line-overlap correction .....	21
11.2	Background correction .....	21
11.3	Drift correction .....	22
11.4	Calculation of results .....	22
11.5	Software requirements .....	23
12	Reproducibility and repeatability .....	24
12.1	Fusion tests .....	24
12.2	Frequency of instrument tests .....	24
12.3	Maximum allowance differences of sample holders .....	24
12.4	Sample measuring positions .....	25
12.5	Instrument repeatability .....	25
12.6	Sequential systems .....	25
12.7	Dead time .....	26
12.8	Other tests .....	26
12.9	Flow gas .....	26
13	Accuracy determined by certified reference materials .....	26

13.1	Validation of synthetic calibrations .....	26
13.2	Validation of SeRM calibrations .....	26
13.3	Fresh beads of the CRMs or synthetic standards used to check SeRM calibrations .....	26
14	Definitions of limits of detection .....	27
15	Test report .....	27
Annex A (normative) Calibration range and required detection limits .....		28
Annex B (normative) Corrections for tungsten carbide grinding media .....		32
Annex C (informative) Examples of fluxes/flux ratios .....		34
Annex D (normative) Examples of CRM to be used to check synthetic calibrations .....		36
Annex E (normative) Examples of SeRM .....		42
Annex F (normative) Equation for theoretical calculations .....		47
Annex G (normative) Certified reference materials (CRMs) .....		48
Annex H (normative) Method of inter-element correction used to compensate for the effects of co-existing components when using SeRM for calibration .....		51
Annex I (normative) Standard deviations achieved with certified reference materials .....		72
Bibliography .....		79