

DIN EN ISO 7539-6:2012-01 (E)

Corrosion of metals and alloys - Stress corrosion testing - Part 6: Preparation and use of precracked specimens for tests under constant load or constant displacement (ISO 7539-6:2011)

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Terms and definitions	5
4	Principle	7
5	Specimens	8
5.1	General	8
5.2	Specimen design	9
5.3	Stress intensity factor considerations	20
5.4	Specimen preparation	25
5.5	Specimen identification	26
6	Initiation and propagation of fatigue cracks	26
7	Procedure	28
7.1	General	28
7.2	Environmental considerations	28
7.3	Environmental chamber	29
7.4	Environmental control and monitoring	30
7.5	Determination of KISCC by crack arrest	31
7.6	Determination of KISCC by crack initiation	34
7.7	Measurement of crack velocity	35
8	Test report	36
Annex A (normative) Use of notched specimens for stress corrosion tests		38
Annex B (normative) Determination of crack growth velocity		41