

ISO 17636-2:2013-01 (E)

Non-destructive testing of welds - Radiographic testing - Part 2: X- and gamma-ray techniques with digital detectors

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Symbols and terms	5
5	Classification of radiographic techniques	6
6	General	7
6.1	Protection against ionizing radiation	7
6.2	Surface preparation and stage of manufacture	7
6.3	Location of the weld in the radiograph	8
6.4	Identification of radiographs	8
6.5	Marking	8
6.6	Overlap of digital images	8
6.7	Types and positions of image quality indicators (IQI)	8
6.8	Minimum image quality values	9
6.9	Personnel qualification	10
7	Recommended techniques for making digital radiographs	10
7.1	Test arrangements	10
7.2	Choice of tube voltage and radiation source	16
7.3	Detector systems and metal screens	18
7.4	Alignment of beam	20
7.5	Reduction of scattered radiation	20
7.6	Source-to-object distance	22
7.7	Geometric magnification technique	25
7.8	Maximum area for a single exposure	26
7.9	Processing	26
7.10	Monitor viewing conditions and storage of digital radiographs	27
8	Examination report	28
Annex A (normative)	Recommended number of exposures which give an acceptable examination of a circumferential butt weld	30
Annex B (normative)	Minimum image quality values	35
Annex C (normative)	Determination of basic spatial resolution	41
Annex D (normative)	Determination of minimum grey values for CR practice	45
Annex E (informative)	Grey values, general remarks	50
Bibliography		52