

DIN EN ISO 9717:2013-07 (E)

Metallic and other inorganic coatings - Phosphate conversion coating of metals (ISO 9717:2010)

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	6
4	Information to be supplied by the purchaser to the processor	7
4.1	Essential information	7
4.2	Additional information	7
5	Designation	7
5.1	General	7
5.2	Designation specifications	8
5.3	Designation of heat treatment requirements	8
5.4	Classification of phosphate conversion coating	9
6	Requirements	10
6.1	Surface preparation	10
6.2	Phosphate conversion coating	10
6.3	Processing after phosphating	10
6.4	Thickness of coating	11
6.5	Stress-relief heat treatment before cleaning and phosphating	12
6.6	Hydrogen-embrittlement-relief heat treatment after phosphating	12
6.7	Treatments for supplementary coatings	12
6.8	Adhesion of phosphate conversion coatings	13
6.9	Quality-evaluation test of phosphate conversion coatings	13
7	Sampling	13
Annex A (informative)	Methods of application, characteristics and significance of phosphate conversion coatings	14
Annex B (informative)	Determination of rinse-water contamination	17
Annex C (informative)	Identification of phosphate conversion coating	19
Annex D (normative)	Salt droplet test	21
Annex E (normative)	Determination of resistance of phosphate conversion coating to neutral salt spray (fog) test	24
Annex F (normative)	Treatments for supplementary coating	26
Bibliography		27