

ISO 12110-1:2013-07 (E)

Metallic materials - Fatigue testing - Variable amplitude fatigue testing - Part 1: General principles, test method and reporting requirements

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Principle of test	4
4.1	Control signal generation	4
4.2	Overview of test procedure	4
5	Original loading time history	5
5.1	General	5
5.2	Data filtering	5
6	Loading time history description	6
6.1	General	6
6.2	Time history sequences description	6
6.3	Cycle counting description	6
7	Programmed blocks	7
8	Transition matrix and generation of control signal from the matrix	7
8.1	Establishment of the matrix	7
8.2	Reconstruction of the loading signal	8
8.3	Control signal simplification	9
9	Conducting fatigue testing under variable amplitude conditions	9
10	Test report for each individual specimen	10
10.1	General	10
10.2	Original loading description	10
10.3	Testing conditions	10
10.4	Preliminary analysis of test data for each specimen and for a series of specimens	12
Annex A (informative) Standard loading time histories		18
Annex B (informative) Example of loading signal reconstruction by random draw in the transition matrix		19
Annex C (informative) Preliminary analysis of test data on a single specimen		21
Bibliography		24