

# ISO 12110-1:2013-07 (E)

## Metallic materials - Fatigue testing - Variable amplitude fatigue testing - Part 1: General principles, test method and reporting requirements

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	2
4	Principle of test .....	4
4.1	Control signal generation .....	4
4.2	Overview of test procedure .....	4
5	Original loading time history .....	5
5.1	General .....	5
5.2	Data filtering .....	5
6	Loading time history description .....	6
6.1	General .....	6
6.2	Time history sequences description .....	6
6.3	Cycle counting description .....	6
7	Programmed blocks .....	7
8	Transition matrix and generation of control signal from the matrix .....	7
8.1	Establishment of the matrix .....	7
8.2	Reconstruction of the loading signal .....	8
8.3	Control signal simplification .....	9
9	Conducting fatigue testing under variable amplitude conditions .....	9
10	Test report for each individual specimen .....	10
10.1	General .....	10
10.2	Original loading description .....	10
10.3	Testing conditions .....	10
10.4	Preliminary analysis of test data for each specimen and for a series of specimens .....	12
Annex A (informative)	Standard loading time histories .....	18
Annex B (informative)	Example of loading signal reconstruction by random draw in the transition matrix .....	19
Annex C (informative)	Preliminary analysis of test data on a single specimen .....	21
Bibliography .....		24